

Menu

HISTORY FILE MAP for year 2004

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

Heavy rain at DSS45 resulted in the following data outages. DR C103656 refers:

171.07:19-07:44 25m RT 4096bps plus
(170.16:28-18:29) 2h01m 512bps PB data plus
(170.18:35-18:57) 21m 512bps PB data plus
171.08:28-08:40 12m RT 4096bps plus
(170.10:56-12:08) 1h13m 512bps PB data.



172.07:20-07:28 7m RT 1024bps data lost due to long 1-way to 2-way transition at DSS34. No DR was raised.

172.17:22-17:56 35m RT 1024bps data lost due to suspected azimuth encoder failure at DSS55. DSS54 antenna brought up to support. DR M102553 refers.